



Photo 1: Looking SE – Possible location of hard mast tree plantings.



Photo 2: Looking S – Propose location of well near willow thicket (to the west)



Photo 3: Looking west – RR crossing. Coin Pond in the background



Photo 4: Looking NE – Hard Mast tree planting area



Photo 5: Looking SW – Hard Mast Tree planting area



Photo 6: Looking East – Existing CMP drainage/washed out access road.



Photo 7: Looking West - Existing CMP drainage/washed out access road.



Photo 8: Existing CMP



Photo 9: Looking Upstream of Fox River at existing CMP location.



Photo 10: Looking West – Location where earth was built up to prevent Fox River overflowing in a westward direction during high water events. It is speculated by Dave Ellis that this overflow is what causes the erosion at the existing CMP site downstream.



Photo 11: Looking US on the Fox River from same location as Photo 10.



Photo 12: Looking DS on the Fox River from same location as Photo 10.



Photo 13: Looking South – Forest regeneration area



Photo 14: Looking South – Slim Slough



Photo 15: Looking North – Slim Slough



Photo 16: Looking South - Rose Pond Conservation Area



Photo 17: Looking South - Rose Pond Conservation Area



Photo 18: Rose Pond Conservation Area



Photo 19: Looking SW - Logsden Tract proposed native grasses



Photo 20: Looking North - Logsden Tract (west of levee)



Photo 21: Looking East towards levee - Logsden Tract (west of levee)



Photo 22: Logsden Tract – abandoned well



Photo 23: Logsden Tract – East side of levee proposed forest regeneration



Photo 24: Logsden Tract – Logsden Slough



Photo 25: Water on west side of levee just before right turn off of levee onto farm road. Water had an unusual reddish tint to it.